



### Gear Leg Drawings

Typical layout for machining:



Typical nose strut:



Isometric:

